

October 30, 2009

We are sorry to announce that we have discontinued the 37 pin count option for the following series:

K85R1X-C37P  
K85R1X-C37S

K85R2X-C37P  
K85R2X-C37S

We can still offer the other pin counts within these series.